

District Report

Ramechhap

11 – 25 May 2018

Activity Summary

Activity	Contact Person	Reference Document
Ramechhap team has successfully completed Joint Monitoring field from 16-18 May 2018 at Doramba Rural Municipality.	Prakash Bishwakaram dc.ramechhap@hrrpnepal.org	Click Here for field visit report
Ramechhap team has participated in the interaction program organized by CLPIU-GMARI on 11 th May 2018 at District Coordination committee, Manthali, Ramechhap. The interaction program was focused on interaction between the organization working in the reconstruction in the district. All the organization working in the reconstruction was presented their working modality and budget of the program. In the program all the non-government organization and government organization working in the reconstruction were actively presence.	Prakash Bishwakram dc.ramechhap@hrrpnepal.org	
Coordination with New NRA chief and discussion about the reconstruction status of District. Also, discussion about the general coordination meeting and made final date for the general coordination meeting.	Prakash Bishwakaram dc.ramechhap@hrrpnepal.org	
4W update	Jawed Mohamad Im.ramechhap@hrrpnepal.org	Click Here for 4w R56
Contact list update	Jawed Mohamad Im.ramechhap@hrrpnepal.org	Click Here for Contact List

Upcoming Events & Meetings

Event / Meeting	Date, Time, and Location	Contact Person
General Coordination Meeting	29 th May 2018, Tuesday, 11 am – 1 pm, District Technical Office, Manthali Ramechhap.	Prakash Bishwakaram dc.ramechhap@hrrpnepal.org

To include details of upcoming events and meetings in the next bulletin, please share details with techcord.ramechhap@hrrpnepal.org by COB Wednesday of each week.

Field Visit Reports

Date	Location	Participants
16-18 May 2018	Doramba Rural Municipality	<ul style="list-style-type: none"> M&E Consultant (Janak Raj Joshi), DSE (Keshav Raj Pandey), NRA Engineer (Roshan Kumar Yadav), HRRP DTC (Tulasi Ram Lamichhane)

Objective(s)
<ul style="list-style-type: none"> To observe the housing construction in Doramba Rural Municipality To interact with the people's representatives and DLPIU Technical persons To observe the non-compliance houses

Summary	Description of field visit (maximum 300 words)
---------	--

The team of M&E Consultant, District Support Engineer, NRA Engineer and HRRP District Technical coordinator made a visit to Doramba and Tokarpur of Doramba Rural Municipality. The team observed the houses being constructed in the Rural Municipality. About 80% of the houses have been completed up to plinth level. Major houses have been constructed as per the building norms of Nepal Government. After observing the constructed houses, the team interacted with the locally elected bodies and the technical personnel of the wards. Also, the issues of noncompliance houses were discussed with the locally elected bodies. About 13 noncompliance houses were recorded in Tokarpur of Doramba Rural Municipality which was observed by district support engineer and the solutions for those houses will be provided soon. Also during the visit, the houses constructed using different materials as per design catalogue volume 2 were observed. The houses were constructed using interlocking blocks. Also, the houses constructed using cutting stones were observed. The both houses have been promoted by Buildup Nepal.

Challenges / Issues Identified	Action Required	Responsible	Timeframe
The coming monsoon will obstruct the roads for materials transportation	Stack the materials and upgrade roads	Owner and RM	ASAP

Photos



Caption: The team interacting with the chairperson of Khadadevi Rural Municipality. The office was visited by the team during the travel to Doramba Rural Municipality.



Caption: The interaction with the ward members and technical personnel on Doramba of Doramba Rural Municipality

Housing Typology Report



Caption: The house of Manmaya Magar of Dimipokhari, Sunapati Rural Municipality-2 being constructed. The house has been constructed using brick in cement mortar. The house consists of four rooms. The house has been provided with passage of 4'. The doors have been installed within 2' from the corners. The door and windows have not been provided at the same level. The owner has not received any tranches of reconstruction grant.



Caption: The house of Amrita Thapa Magar of Dimipokhari, Sunapati Rural Municipality-2 being constructed. The house has been constructed using interlocking blocks. The house has two rooms. The owner has received second tranche of reconstruction grant. The house has been constructed in 5 lakhs.



Caption: The house of Bhakta Laxmi Thapa Magar of Dimipokhari of Sunapati Rural municipality-2. The house has been constructed using brick in cement mortar. The house consists of two rooms. The owner has not received all three tranches of reconstruction grant.



Caption: The house of Nar bahadur Magar of Dimipokhari of Sunapati Rural municipality-2. The house has been constructed using stone in mud mortar. RC band has been provided to the house. The house consists of two rooms. The owner has received second tranche of reconstruction grant.



Caption: The house of Salam Tamang of Doramba of Doramba Rural municipality. The house has been constructed using stone in mud mortar. RC band has been provided to the house. The house consists of two rooms. Columns have been provided to the building at the corner. The owner has received second tranche of reconstruction grant.



Caption: The house of Kale Tamang of Doramba of Doramba Rural municipality. The house has been constructed using stone in mud mortar. RC band has been provided to the house. The house consists of three rooms. The owner has received second tranche of reconstruction grant and have been forwarded for third tranche.