

District Report

Kavrepalanchok

28 September-5 October 2017

Activity Summary		
Activity	Contact Person	Reference Document
Meeting Calendar Update	Reshma Shrestha	HRRP Website
HRRP Coordination Meeting	Reshma Shrestha	
Planning		

Upcoming Events & Med	etings	
Event / Meeting	Date, Time, and Location	Contact Person
HRRP Coordination Meeting	10/09/2017, 11:30 AM, Dhulikhel	Reshma Shrestha

Field Visit Repor	rts			
Date		Location	Participants	
6th October 2017		Ojhetar, Panchkhal Municipality	HRRP Technical Officer, Kuber Bogati	
			 HRRP Kavre, Reshma Shrestha 	
Objective(s)	 For detailed study and measurements of Adobe constructions in Ojheta 		nents of Adobe constructions in Ojhetar,	
	P	anchkhal Municipality.		
	1			
	During the Field Visit conducted by HRRP Kavre to Ojhetar on 7th September 2017,			
	preliminary information was collected on the completed and ongoing Adobe			
	constructions. As the adobe structures are covered by the National Building Code of			
	Nepal but not considered for the reconstruction program, more details were required.			
Summary	So, the houses visited during the earlier visits were measured and studied in detail.			
	One of the construction with RCC band was found to be in compliance to the national			
	building code. Through general observation, most all of the constructions in adobe			
	with wooden band missed one or more components, but conclusions can be drawn			
	after the detail analysis of the information collected.			
DI I				

Photos



5 October 2017 Page 1 of 2

District ReportHousing Recovery and Reconstruction Platform, Nepal



This house sees all the earthquake resistant elements but
the construction is on adobe. The house owner Pushpa
Maya Danuwar has received the municipal permit for this
design as well. (Ojhetar, Panchkhal Municipality)

Page 2 of 2 5 October 2017